

Dirty customer CAD in. Production-ready G-code out.

- **True arcs, never polylines**

Exploded curves re-fit into real G2/G3 arcs. A circle posts as a circle.

- **Every program audited**

Each cut move checked against the source file before it ships.

- **Reads what customers send**

DXF, DWG, Illustrator .ai and PDF, all the way to G-code.

- **Safe cut order**

Pierces kept off finished edges. Outer profile always last.

Aristide Abrahams

aristide@kerfmaster.com · 734 679 6102

29035 5 Mile Road, Livonia, MI 48154



SCAN TO SEE IT
KERFMASTER.COM