


A circle should post as a **circle**.

Not 300 tiny lines. Kerfmaster re-fits exploded customer curves into real G2/G3 arcs, then audits every move against the source file.



CUSTOMER FILE: 14 LINES **KERFMASTER: 1 ARC**

G03 X1.7500 Y1.0000 I-0.7500 J0.0000 (**one true arc**)

Software for laser job shops.

Aristide Abrahams

aristide@kerfmaster.com · 734 679 6102

29035 5 Mile Road, Livonia, MI 48154



SCAN · KERFMASTER.COM